


Old Auburn/Fair Oaks Intersection: Collision Statistics


Many of the collisions that occurred at Old Auburn Road/Fair Oaks Boulevard involved vehicles that were making the northbound left-turn from Fair Oaks Boulevard onto Old Auburn Road.

Collision Statistics (2006-2018):



16 collisions involved vehicles making the north-bound left-turn and colliding with the planter barriers

Of those collisions



15 of 16 involved only one vehicle



11 of 16 occurred during rainy/wet conditions



5 of 16 occurred during nighttime/dark conditions



5 of 16 occurred due to driver impairment

Old Auburn/Fair Oaks Collisions

This map shows injury collisions (source: SWITRS, 2006-2018) and property damage collisions (source: TIMS, 2013-2018).

